DESERT RIDGE Community Improvement Projects













Click on an image to enlarge with more details

142 utility cabinets were

painted Mesa Tan by





HOLD OUR HILLS erosion control project 12/2022 - 12/2023 in 6 phases

Removed silt-filled RR tie dams, reconfigured spillway channels, added new 24" wide border channels inside-curbs - 8" rip rap rock fill prevents street spillover.

G.V. Decorative, larger 1" flow-slowing Coronado Brown rock, now covers common area hillsides behind 26 affected lots and 13 islands.

Using 520 tons of 1" and 156 tons of 8" rip rap, Total HOA cost: \$90,215. including \$20,440. maintenance-swap labor.

Contractor: Mochomo's - HOA supervisor: Dave Ward

AA Before

HOLD OUR HILLS erosion control - Phase 2 Complete





MITE Attack UPDATE

Your neighbor-volunteers have cut-back and sprayed all of the infected Texas Rangers in the common areas. Weekly spraying will continue for a total of 3 applications.



Eriophyid Mite Microscopic - too tiny to see



All of the refuse was hauled off by Mochomo's, our Maintenance contractor.

Homeowner - Now it's your turn!
PLEASE inspect the Texas Rangers in your
front yard and inside your fences for infection.
See examples on next page.
Cut back infected plants to 24" high.

REGARDLESS...

DRENCH spray **ALL** your plants with the DAWN/ water spray - 3 times - Weekly starting March 1.


Sidewalk Renovations



Four signs were installed in February 2021

Flashing SPEED LIMIT sign locations: (See PLAT for extrapolated street number locations)

Southeast entry [2698 S Desert Ridge]
Central westbound [876 W Desert Hills Dr]
Central eastbound [969 W Desert Hills Dr]
West entry [1089 W Desert Hills Dr]



Utility Cabinet Repainting - May 2019

142 cabinets in 55 locations




Signage Changes





New Entry Sign Lettering & Light Bars - April 2018



Entry Sign Lighting Converted to Solar Power November 2014

